


## 中心孔式十字盘头机螺钉



|    | M3  | M4  | M5  | M6   |
|----|-----|-----|-----|------|
| dk | 5.5 | 7   | 9   | 10.5 |
| k  | 2   | 2.6 | 3.3 | 3.9  |
| A  | 1.2 | 1.5 | 1.5 | 2    |



绿色环保指示

## ●材料

不锈钢 A2

件 / 箱

| L \ d | M3 | M4 | M5 | M6 |
|-------|----|----|----|----|
| 5     | 20 | 20 |    |    |
| 6     | 20 | 20 | 10 |    |
| 8     | 20 | 20 | 10 | 10 |
| 10    | 20 | 20 | 10 | 10 |
| 12    | 20 | 20 | 10 | 10 |
| 16    |    | 20 | 10 | 10 |
| 20    |    |    | 10 | 10 |
| 25    |    |    |    | 10 |


## ●材料

不锈钢 A2, 特殊化学抛光

件 / 箱

| L \ d | M3 | M4 | M5 | M6 |
|-------|----|----|----|----|
| 5     | 20 | 20 |    |    |
| 6     | 20 | 20 | 10 |    |
| 8     | 20 | 20 | 10 | 10 |
| 10    | 20 | 20 | 10 | 10 |
| 12    | 20 | 20 | 10 | 10 |
| 16    |    | 20 | 10 | 10 |
| 20    |    |    | 10 | 10 |
| 25    |    |    |    | 10 |

## 中心孔式十字平头机螺钉



|    | M3   | M4  | M5  | M6  |
|----|------|-----|-----|-----|
| dk | 6    | 8   | 10  | 12  |
| k  | 1.75 | 2.3 | 2.8 | 3.4 |
| A  | 1.2  | 1.5 | 1.5 | 2   |



绿色环保指示

## ●材料

不锈钢 A2

件 / 箱

| L \ d | M3 | M4 | M5 | M6 |
|-------|----|----|----|----|
| 5     | 20 | 20 |    |    |
| 6     | 20 | 20 | 10 |    |
| 8     | 20 | 20 | 10 | 10 |
| 10    | 20 | 20 | 10 | 10 |
| 12    | 20 | 20 | 10 | 10 |
| 16    |    | 20 | 10 | 10 |
| 20    |    |    | 10 | 10 |
| 25    |    |    |    | 10 |

## ●材料

不锈钢 A2, 特殊化学抛光

件 / 箱

| L \ d | M3 | M4 | M5 | M6 |
|-------|----|----|----|----|
| 5     | 20 | 20 |    |    |
| 6     | 20 | 20 | 10 |    |
| 8     | 20 | 20 | 10 | 10 |
| 10    | 20 | 20 | 10 | 10 |
| 12    | 20 | 20 | 10 | 10 |
| 16    |    | 20 | 10 | 10 |
| 20    |    |    | 10 | 10 |
| 25    |    |    |    | 10 |