


六角盖帽螺钉 JIS B1180 附件 [全螺纹]



请从 RoHS 指示



- 材料：铁
- 表面处理：三价镀锌
黑色三价镀锌



| | M3 | M4 | M5 | M6 | M8 | M10 | M12 | M14 | M16 |
|---|-----|-----|-----|----|-----|-----|-----|-----|-----|
| s | 5.5 | 7 | 8 | 10 | 13 | 17 | 19 | 22 | 24 |
| k | 2 | 2.8 | 3.5 | 4 | 5.5 | 7 | 8 | 9 | 10 |

BOLT

| | | 件 / 箱 | | | | | | | |
|-------|------|-------|------|-----|-----|-----|-----|-----|-----|
| L \ d | M3 | M4 | M5 | M6 | M8 | M10 | M12 | M14 | M16 |
| 6 | 5000 | 2000 | 1000 | | | | | | |
| 8 | 5000 | 2000 | 1000 | 500 | | | | | |
| 10 | 4000 | 1000 | 1000 | 800 | 300 | | | | |
| 12 | 2000 | 1000 | 1000 | 800 | 400 | | | | |
| 14 | | 1000 | 1000 | 800 | 350 | | | | |
| 15 | 2000 | 1000 | 1000 | 700 | 350 | 200 | | | |
| 16 | 2000 | 1000 | 1000 | 700 | 350 | 200 | | | |
| 18 | | 1000 | 500 | 700 | 300 | | | | |
| 20 | 1000 | 1000 | 500 | 600 | 300 | 200 | 100 | | |
| 22 | 1000 | 1000 | 500 | 600 | | | | | |
| 25 | 1000 | 1000 | 500 | 600 | 300 | 200 | 100 | 100 | 70 |
| 30 | 1000 | 1000 | 500 | 500 | 300 | 200 | 100 | 90 | 60 |
| 35 | 1000 | 500 | 500 | 450 | 200 | 150 | 100 | 80 | 50 |
| 40 | | 500 | 500 | 400 | 250 | 100 | 100 | 70 | 50 |
| 45 | | 500 | 200 | 350 | 250 | 100 | 100 | 70 | 50 |
| 50 | | 200 | 200 | 300 | 250 | 100 | 100 | 60 | 50 |
| 55 | | | 200 | 250 | 200 | 100 | 50 | 50 | 40 |
| 60 | | | 200 | 250 | 200 | 100 | 50 | 50 | 40 |
| 65 | | | 200 | 250 | 200 | 100 | 50 | 50 | 40 |
| 70 | | | | 200 | 100 | 100 | 50 | 50 | 40 |
| 75 | | | | 200 | 100 | 100 | 50 | 50 | 40 |
| 80 | | | | 250 | 100 | 100 | 50 | 40 | 40 |
| 85 | | | | | 150 | | | | |
| 90 | | | | 200 | 150 | 90 | 50 | 40 | 40 |
| 100 | | | | 200 | 150 | 80 | 50 | 30 | 30 |
| 110 | | | | 200 | 100 | 70 | 50 | | |
| 120 | | | | 150 | 100 | 70 | 50 | | |
| 130 | | | | 150 | 100 | 60 | 40 | | |
| 140 | | | | 150 | 100 | 60 | 40 | | |
| 150 | | | | 150 | 100 | 60 | 40 | | |




六角盖帽螺钉

JIS B1180 附件

[全螺纹]



符合 RoHS 指令



●材料
不锈钢 A2



| | M3 | M4 | M5 | M6 | M8 | M10 | M12 | M14 | M16 | M18 | M20 | M24 | M30 |
|---|-----|-----|-----|----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| s | 5.5 | 7 | 8 | 10 | 13 | 17 | 19 | 22 | 24 | 27 | 30 | 36 | 46 |
| k | 2 | 2.8 | 3.5 | 4 | 5.5 | 7 | 8 | 9 | 10 | 12 | 13 | 15 | 19 |

| L \ d | 件 / 箱 | | | | | | | | | | | | |
|-------|-------|------|------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| | M3 | M4 | M5 | M6 | M8 | M10 | M12 | M14 | M16 | M18 | M20 | M24 | M30 |
| 6 | 2000 | 1000 | 1000 | | | | | | | | | | |
| 8 | 2000 | 1000 | 1000 | 700 | | | | | | | | | |
| 10 | 2000 | 1000 | 1000 | 400 | 200 | | | | | | | | |
| 12 | 2000 | 1000 | 500 | 400 | 200 | | | | | | | | |
| 14 | | 1000 | 500 | 400 | 200 | | | | | | | | |
| 15 | 1500 | 1000 | 500 | 400 | 200 | 100 | | | | | | | |
| 16 | 1500 | 1000 | 500 | 400 | 200 | 100 | | | | | | | |
| 18 | | 500 | 500 | 300 | 200 | 100 | | | | | | | |
| 20 | 1000 | 500 | 500 | 300 | 200 | 100 | 100 | | | | | | |
| 22 | | | 500 | 300 | 200 | | | | | | | | |
| 25 | 1000 | 500 | 300 | 300 | 200 | 100 | 100 | 50 | 50 | | | | |
| 30 | 1000 | 500 | 300 | 300 | 100 | 100 | 100 | 50 | 50 | 40 | 35 | | |
| 35 | 1000 | 300 | 300 | 300 | 100 | 100 | 100 | 100 | 50 | 40 | 35 | | |
| 40 | 1000 | 300 | 200 | 300 | 100 | 100 | 100 | 50 | 50 | 40 | 35 | | |
| 45 | | 300 | 200 | 200 | 100 | 100 | 100 | 50 | 50 | 30 | 30 | | |
| 50 | | 200 | 200 | 200 | 100 | 100 | 50 | 50 | 50 | 30 | 30 | | 12 |
| 55 | | 200 | 200 | 200 | 100 | 100 | 50 | 50 | 40 | 30 | 25 | | 12 |
| 60 | | 200 | 200 | 200 | 100 | 100 | 50 | 50 | 30 | 30 | 25 | 20 | 10 |
| 65 | | | 200 | 200 | 100 | 100 | 50 | 40 | 30 | 25 | 25 | 20 | 10 |
| 70 | | | 150 | 100 | 100 | 50 | 50 | 40 | 30 | 25 | 20 | | 10 |
| 75 | | | 150 | 100 | 100 | 50 | 50 | 40 | 30 | 25 | 20 | | |
| 80 | | | 150 | 100 | 100 | 50 | 50 | 30 | 30 | 25 | 20 | | |
| 85 | | | 150 | 100 | 100 | 50 | 50 | | 30 | | 20 | | |
| 90 | | | 100 | 100 | 100 | 50 | 50 | 30 | 30 | 20 | 20 | | |
| 100 | | | 100 | 100 | 100 | 50 | 50 | 30 | 30 | 20 | 20 | | |
| 110 | | | | 150 | 50 | 50 | 25 | | 20 | | 15 | | |
| 120 | | | | 150 | 50 | 50 | 40 | | 20 | | 15 | | |
| 130 | | | | 150 | 50 | 50 | 30 | | 20 | | 15 | | |
| 140 | | | | 150 | 50 | 50 | 30 | | 20 | | 15 | | |
| 150 | | | | 150 | 50 | 50 | 30 | | 20 | | 15 | | |
| 160 | | | | | 50 | 40 | 30 | | 15 | | | | |
| 170 | | | | | 50 | 40 | 30 | | 15 | | | | |
| 180 | | | | | 50 | 40 | 30 | | 15 | | | | |
| 190 | | | | | 50 | 40 | 30 | | | | | | |
| 200 | | | | | 50 | 40 | 30 | | 15 | | | | |
| 210 | | | | | | | 25 | | | | | | |
| 220 | | | | | | | 25 | | 10 | | | | |
| 230 | | | | | | | 25 | | | | | | |
| 250 | | | | | | 30 | 25 | | 10 | | | | |
| 300 | | | | | | 30 | 25 | | 10 | | | | |

BOLT

