


六角盖帽螺钉 JIS B1180 附件



●材料

钛



| | M4 | M5 | M6 | M8 | M10 | M12 | M16 | M20 |
|---|-----|-----|----|-----|-----|-----|-----|-----|
| s | 7 | 8 | 10 | 13 | 17 | 19 | 24 | 30 |
| k | 2.8 | 3.5 | 4 | 5.5 | 7 | 8 | 10 | 13 |



遵从 RoHS 指示

| L \ d | M4 | M5 | M6 | M8 | M10 | M12 | M16 | M20 |
|-------|-----|-----|-----|-------|-------|------|------|------|
| 8 | 200 | 200 | | | | | | |
| 10 | 200 | 200 | 200 | | | | | |
| 12 | 200 | 200 | 200 | | | | | |
| 16 | 200 | 200 | 200 | 100 | | | | |
| 20 | 200 | 200 | 200 | 100 | 50 | 50 | | |
| 25 | 200 | 200 | 200 | 100 | 50 | 50 | | |
| 30 | 200 | 200 | 200 | 100 | 50 | 50 | 20 | |
| 35 | 200 | 200 | 200 | 100 | 50 | 50 | 20 | |
| 40 | 200 | 200 | 200 | 100 | 50 | 50 | 20 | |
| 45 | 200 | 200 | 200 | 100 | 50 | * 50 | 20 | |
| 50 | 200 | 200 | 200 | 100 | 50 | * 50 | * 20 | 15 |
| 55 | | | 200 | 100 | * 50 | * 50 | * 20 | * 15 |
| 60 | | | 200 | 100 | * 50 | * 50 | * 20 | * 15 |
| 65 | | | | * 100 | * 50 | * 50 | * 20 | * 15 |
| 70 | | | | * 100 | * 50 | * 50 | * 20 | * 15 |
| 75 | | | | | * 100 | * 50 | * 20 | * 15 |
| 80 | | | | | * 100 | * 50 | * 20 | * 15 |
| 85 | | | | | | * 50 | | * 15 |
| 90 | | | | | * 100 | * 50 | * 20 | * 15 |
| 100 | | | | | * 100 | * 50 | * 20 | * 15 |
| 110 | | | | | | | * 50 | * 15 |
| 120 | | | | | | | * 50 | * 15 |
| 130 | | | | | | | * 50 | * 15 |
| 140 | | | | | | | * 20 | * 15 |
| 150 | | | | | | | * 20 | * 15 |

* ... 半螺纹