


十字盘头机螺钉 JIS B1111 附件



●材料

钛



	M3	M4	M5	M6
dk	5.5	7	9	10.5
k	2	2.6	3.3	3.9



遵从RoHS指示

件 / 箱

L \ d	M3	M4	M5	M6
6	500	300		
8	500	300	200	
10	500	300	200	100
12	500	300	200	100
15	500	300	200	100
16	500	300	200	100
20	500	300	200	100
25	500	300	200	100
30	500	300	200	100
35		300	200	100
40		300	200	100
45			200	100
50			200	100
60				100

钛：纯净的钛 JIS H4670 TW270 or TW340.